
















That must meet ALL of the requirements of one of the following rows.

Standard and Date	Quality Assurance Mark	Examples
<p>1</p> <p>PAS 015 2011</p>	<p>AND MUST HAVE</p> <p>BSI Kitemark</p>  <p>Or Inspec IC Mark</p> 	
<p>2</p> <p>VG1 01.040 (2014-12)</p>	<p>AND MUST HAVE</p> <p>BSI Kitemark</p>  <p>Or Inspec IC Mark</p> 	   
<p>3</p> <p>ASTM F1163 (2004a or 04a onwards)</p>	<p>AND MUST HAVE</p> <p>SEI mark</p> 	  
<p>4</p> <p>SNELL E2016</p>	<p>AND MUST HAVE</p> <p>Official SNELL label and number</p> 	
<p>5</p> <p>AS/NZS 3838 (2006 onwards)</p>	<p>AND MUST HAVE</p> <p>SAI Global mark</p> 